

ADEQ

Hazardous Waste Division

Technical Branch

Trip Report

Project	Former Cedar Chemical Facility
Location	West Helena, AR
Date	03/21/2012
Time	day trip
Reason	Due to the proposal to add Cedar Chemical to the EPA National Priority List, the EPA representative, Philip Allen came to visit the site.
ADEQ personnel	Clay McDaniel, Jim Rigg, Jeremiah Jackson, Dara Hall
Facility personnel	Gary Hill – Harcross employee Stanley Herrington – Harcross Site Manager
Activity Summary	We walked throughout the facility with Philip and Stanley to apprise Philip on site conditions.
Action Items Summary	<ul style="list-style-type: none"> Stanley indicated the soil pile (see photo #3) was generated mainly from cleaning out the sump (see photo #4). But it may have also included excavation from the new foundation (see photo #4). Stanley indicated the soil pile will be sent to Clean Harbors for incineration. Part of the foundation of Unit 2 has been jack-hammered out (see photo #2).
Anticipated follow-up	
Other	

Route to:

ADEQ personnel review	date
Annette Cusher	
Tammie Hynum	



9459938

Arkansas Department of Environmental Quality

Official Photograph Log


Unit 1 in Operation

Photo # 1	Photographer: Clay McDaniel, ADEQ
Date: Wednesday, March 21, 2012	Witness: Jeremiah Jackson, ADEQ



Unit 2 Foundation

Photo # 2	Photographer: Clay McDaniel, ADEQ
Date: Wednesday, March 21, 2012	Witness: Jeremiah Jackson, ADEQ



Arkansas Department of Environmental Quality

Official Photograph Log

Soil Pile from Sump Excavation

(located on the former Unit 4 footprint)

Photo # 3

Photographer: Clay McDaniel, ADEQ

Date: Wednesday, March 21, 2012

Witness: Jeremiah Jackson, ADEQ




Unit 1 Sump and Newly Poured Foundation

Photo # 4

Photographer: Clay McDaniel, ADEQ

Date: Wednesday, March 21, 2012

Witness: Jeremiah Jackson, ADEQ



sump is underneath
grated metal